

# ●寸法・質量

呼び名	寸法											参考質量 (kg)	
	h	a	b	c	d	t <sub>1</sub>	t <sub>2</sub>	t <sub>3</sub>	t <sub>4</sub>	r	m		ℓ
0710	700 (h <sub>1</sub> =200)	1000	950	1140	—	70	95	95	—	100	30	2000	1100
0711		1100	1050	1240	1340				1200				
0712		1200	1150	1340	1440				1240				
0713		1300	1250	1440	1540				1290				
0714		1400	1350	1540	1640				1330				
0715		1500	1450	1640	1840				1420				
0716		1600	1550	1740	1940				1460				
0717		1700	1650	1840	2040				1510				
0718		1800	1750	1940	2140				1550				
0719		1900	1850	2040	2240				1600				
0720	2000	1950	2140	2440	1680								
0810	800 (h <sub>1</sub> =250)	1000	950	1140	1240	70	95	95	—	100	30	2000	1220
0811		1100	1050	1240	1340				1270				
0812		1200	1150	1340	1440				1310				
0813		1300	1250	1440	1540				1360				
0814		1400	1350	1540	1740				1450				
0815		1500	1450	1640	1840				1490				
0816		1600	1550	1740	1940				1540				
0817		1700	1650	1840	2040				1580				
0818		1800	1750	1940	2240				1670				
0819		1900	1850	2040	2340				1720				
0820	2000	1950	2140	2440	1760								
0910	900 (h <sub>1</sub> =300)	1000	950	1150	1250	75	100	100	—	100	30	2000	1380
0911		1100	1050	1250	1350				1430				
0912		1200	1150	1350	1450				1470				
0913		1300	1250	1450	1550				1520				
0914		1400	1350	1550	1750				1610				
0915		1500	1450	1650	1850				1660				
0916		1600	1550	1750	1950				1710				
0917		1700	1650	1850	2050				1760				
0918		1800	1750	1950	2250				1850				
0919		1900	1850	2050	2350				1900				
0920	2000	1950	2150	2450	1940								
1010	1000 (h <sub>1</sub> =300)	1000	930	1150	—	75	110	110	—	150	30	2000	1530
1011		1100	1030	1250	1350				1640				
1012		1200	1130	1350	1450				1690				
1013		1300	1230	1450	1550				1750				
1014		1400	1330	1550	1650				1800				
1015		1500	1430	1650	1850				1900				
1016		1600	1530	1750	1950				1950				
1017		1700	1630	1850	2050				2000				
1018		1800	1730	1950	2150				2060				
1019		1900	1830	2050	2350				2160				
1020	2000	1930	2150	2450	2210								
1111	1100 (h <sub>1</sub> =350)	1100	1030	1260	1360	80	115	115	—	150	30	2000	1820
1112		1200	1130	1360	1460				1870				
1113		1300	1230	1460	1560				1930				
1114		1400	1330	1560	1660				1980				
1115		1500	1430	1660	1860				2090				
1116		1600	1530	1760	1960				2150				
1117		1700	1630	1860	2060				2200				
1118		1800	1730	1960	2160				2250				
1119		1900	1830	2060	2360				2360				
1120		2000	1930	2160	2460				2410				
1121	2100	2030	2260	2560	2470								
1212	1200 (h <sub>1</sub> =400)	1200	1120	1370	1470	85	125	125	—	150	30	2000	2120
1213		1300	1220	1470	1570				2180				
1214		1400	1320	1570	1670				2240				
1215		1500	1420	1670	1770				2300				
1216		1600	1520	1770	1970				2420				
1217		1700	1620	1870	2070				2470				
1218		1800	1720	1970	2170				2530				
1219		1900	1820	2070	2270				2590				
1220		2000	1920	2170	2470				2710				
1221		2100	2020	2270	2570				2770				
1222	2200	2120	2370	2670	2820								
寸法の 許容差	+6 -4	±7				+5 -2		+6 -2		-	-	±5	-